Manhole In	spection Summary	Manhole # S01EE2009MH
Printed On: 12/1	7/2008	Page 1 of 3
Inspection	☐ Is Incomplete Rating: 3) Fair	
Record Plat: 01	EE2 Node: 009 Status: Found	Insp Date: 7/21/06 7:20 AM
Incomplete Cor	nments	Crew: CH, IJ
		Inspector: Hale, C
		Firm: RKK
Location	Address: 3013 Temple Gate	Cross Street: Benhurst Rd
Manhole	Type: Inline Location: Roadway	Ground Conditions: Dry
	Prev. Rehab Weather: Dry	Subject To Ponding: None
Comments	cleaning rods in MH	
Cover	·	30 (in.) Length: (in.) Dist A/B Grade: 0 (in.)
Droportion	Type: Sanitary Condition: S	
Properties:		
Frame	Offset: 0 (in.) Condition: So	und Cracked Leaks
Chimney / Fra	me Adjustment	rick ☐ Parged Height: 3 (in.)
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion	on
Infiltration:	None ✓ Joint ☐ Cracks ☐ Mo	rtar Roots Wall
Corbel	Material: Brick	arged Type: Concentric/Eccentric
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion	on Loose Brick Deteriorated
Infiltration:	□ None □ Joint □ Cracks □ N	fortar ☐ Roots <mark>☑ Wall</mark>
Barrel	Material: Brick	arged
Shape:	Circular Diameter: 42 (in.) L	ength: (in.)
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion	n Loose Brick Deteriorated
Infiltration:	□ None □ Joint □ Cracks □ N	fortar ☐ Roots <mark>☑ Wall</mark>
Bench	Exists Material: Brick	☐ Parged ☐ Debris (not Condition related)
Condition:	☐ Sound ☐ Cracked ☐ Root Intrusion	on 🗌 Deteriorated 🔲 Leaks 📝 Debris
Channel	Material: Brick	arged Debris (not Condition related)
Channel E	xposure: Fully Open Junc Dist: 0	nearest .5 ft. Azimuth:
Condition:	☐ Sound ☐ Cracked ☐ Root Intrusion	on Deteriorated Leaks Debris
Steps	Count: 6 Missing: 0 Corroded	
Surcharge	Evidence Of Surcharge Depth:	(ft.) Active Surcharge Present

Manhole Inspection Summary

Manhole # S01EE2009MH

Printed On: 12/17/2008 Page 2 of 3

Location View



debris on bench



Top View



Defect



leaks at joint

Manhole Inspection Summary

Manhole # S01EE2009MH

Printed On: 12/17/2008 Page 3 of 3

8 in. Circular Gravity Sewer Pipe Out @ 12 O'Clock



Rod and Bar (Angled)

Pipe Material: Clay

Invert Depth: 13.50 (ft.) Flow Characteristics: Slow

Deposits: ☐ None ☐ Mud ☐ Sludge ✓ Debris ☐ Grease

Silt Depth: **0.25** (in.) Deposits Extent: **Medium** Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: None

Connects To: **Manhole**Possible Illicit Connection

8 in. Circular Gravity Sewer Pipe In @ 7 O'Clock



Rod and	Bar (Angl	led)
---------	-------	------	-----	---

Pipe Material: Clay

Invert Depth: 13.20 (ft.) Flow Characteristics: Slow

Deposits: ☐ None ☐ Mud ☐ Sludge ✓ Debris ☐ Grease

Silt Depth: **0.125** (in.) Deposits Extent: **Medium** Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: None

Connects To: **Manhole**Possible Illicit Connection